

RECEIVING INSPECTION REPORT

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080009-4

2951 E. COLORADO ST., PASADENA, CALIF.

RECEIVED FROM

DATE REC'D. 1-12-57

P.O. NO. 69065

VENDOR PACKING SLIP NO. 72896

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	QUANTITY		REMARKS	
									ACCEPTED	REJECTED		
25	322	000000	10068	0	0	00	00	02		20	5	RET # 3609
DRAWING NO. AND DESCRIPTION												
730109-5 CAPACITOR 96F47/92 513												
TO SUPERSEDED REC. # 125034												

RECEIVED
BY

HMC-1089

INSPECTED
BY

DATE

REJECTS RETURNED
ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2751 E. COLORADO ST., PASADENA, CALIF.

No. 11035

RECEIVED FROM

DATE REC'D. 1-26-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	QUANTITY		REMARKS
									ACCEPTED	REJECTED	
125	322	000000	10034	0	0	00	00			125	
DRAWING NO. AND DESCRIPTION											
737387 WASHER - COOKING ARM											
SHIP 85898											

RECEIVED
BY

HMC-1089

INSPECTED
BY

DATE

REJECTS RETURNED
ON SHIP. MEMO NO.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080009-4